

Unit (9752-9919)	Chimney Sweeps report (June 2023)	Whole	Cap	Cap 2	Middle	Middle 2	Base	Other
9751	9751: Piping Separating at Seam, Cap Very Rusted, Piping Dented Badly							
9753	9753: Spark Arrestor Detached							
9755	9755: Cap Rusty, Pipe Dented Badly							
9757	9757: Pipe and Cap Separated, Cap Very Rusty, Spark Arrestor Clogged, Pipe Rusting Thru, Pipes Dented							
9759	9759: Pipe Separating at Seam, Cap Rusty							
9761	9761: Pipes Loose, Cap Rusty							
9763	9763: Cap Rusty, Spark Arrestor Detached							
9765	9765: Flashing Holes, Cap Rusty							

Unit (9752-9919)	Chimney Sweeps report (June 2023)	Whole	Cap	Cap 2	Middle	Middle 2	Base	Other
9767	9767: Spark Arrestor Damaged, Cap Rusty, Pipes Separated							
9769	9769: Spark Arrestor Slipped, Cap Rusty							
9771	9771: Cap Rusty							
9773	9773: Flashing Damaged, Minor Rust on Cap							
9775	9775: Piping Separating, Cap Very Rusty							
9777	9777: Cap Tilted, Cap Rusty							
9779	9779: Spark Arrestor Detached, Cap Rusty							
9781	9781: Cap Very Rusty, Spark Arrestor Damaged, Pipe Rusting							

Unit (9752-9919)	Chimney Sweeps report (June 2023)	Whole	Cap	Cap 2	Middle	Middle 2	Base	Other
9783	9783: Pipe Dented, Cap Rusty							
9785	9785: Cap Rusty							
9787	9787: Piping Dented, Cap Dented, Cap Rusty, Flashing Damaged							
9791	9791: Spark Arrestor Badly Damaged, Cap Very Rusted, Flashing Damaged							
9793	9793: Cap Very Rusted, Spark Arrestor Damaged							
9795	9795: Spark Arrestor Damaged, Cap Rusty, Pipe Damaged							
9797	9797: Cap Rusty, Chimney Dirty							
9803	9803: Cap Rusty, Flashing Damaged, Chimney Dirty, Pipe Damaged							

Unit (9752-9919)	Chimney Sweeps report (June 2023)	Whole	Cap	Cap 2	Middle	Middle 2	Base	Other
9805	9805: Flashing Damaged, Cap Rusty							
9807	9807: Flashing Badly Damaged, Spark Arrestor Slipped, Cap Rusty							
9809	9809: Pipe Dented, Spark Arrestor Slipped, Cap Rusty							
9811	9811: Spark Arrestor Damaged, Cap Rusty, Pipe Damaged & Rusty							
9813	9813: Cap Rusting, Flashing Damaged							
9815	9815: Cap Rusty, Spark Arrestor Damaged, Flashing Damaged							
9817	9817: Cap Damaged, Flashing Damaged, Cap Rusted							
9818	9818: Cap Tilted, Pipe Damaged, Cap Rusting							

Unit (9752-9919)	Chimney Sweeps report (June 2023)	Whole	Cap	Cap 2	Middle	Middle 2	Base	Other
9819	9819: Flashing Cracked, Cap Rusty							
9820	9820: Pipe Rusting & Damaged, Cap Rusty, Spark Arrestor Slipped							
9821	9821: Cap Very Rusted, Flashing Deteriorating							
9822	9822: Spark Arrestor Slipped, Cap Rusty, Flashing Damaged							
9823	9823: Flashing Deteriorating Slightly							
9824	9824: Cap Damaged, Pipe Separating, Spark Arrestor Very Damaged							
9825	9825: Cap Rusty, Spark Arrestor Bent							
9826	9826: Pipe Dented, Cap Rusty, Flashing Cracks							

Unit (9752-9919)	Chimney Sweeps report (June 2023)	Whole	Cap	Cap 2	Middle	Middle 2	Base	Other
9827	9827: Flashing Cracked, Pipe Altered, Cap Rusty, Pipe Rusting, Spark Arrestor Rusting							
9828	9828: Pipe Rusting Badly, Pipe Dented, Flashing Damaged							
9829	9829: Flashing Cracked, Pipe Small Hole							
9830	9830: Cap Very Rusty, Pipe Very Badly Rusting, Pipe Separating, Spark Arrestor Gone							
9831	9831: Cap Rusty, Pipe Clamp Broken							
9832	9832: Pipe Badly Compromised, Flashing Cracked, Cap Rusty, Spark Arrestor Damaged Broken							
9833	9833: Cap Rusty, Spark Arrestor Damaged							
9834	9834: Cap Bent, Chimney Dirty, Flashing Cracked							

Unit (9752-9919)	Chimney Sweeps report (June 2023)	Whole	Cap	Cap 2	Middle	Middle 2	Base	Other
9835	9835: Cap Rusty, Spark Arrestor Slipped, Pipe Badly Separated, Pipe Rusting							
9836	9836: Cap Rusted, Spark Arrestor Slid							
9837	9837: Cap Rusty, Pipe Dented, Spark Arrestor Damaged, Chimney Dirty							
9838	9838: Cap Rusty, Flashing Cracked							
9839	9839: Cap Dented, Spark Arrestor Rusty							
9840	9840: Cap Rusty, Spark Arrestor Damaged, Pipe Dented, Flashing Badly Cracked							
9841	9841: Pipe Dented, Flashing Poor, Cap and Spark Arrestor Badly Rusted							
9842	9842: Pipe Very Badly Rusted, Flashing Cracked, Spark Arrestor Slipped							

Unit (9752-9919)	Chimney Sweeps report (June 2023)	Whole	Cap	Cap 2	Middle	Middle 2	Base	Other
9843	9843: Cap Rusty, Spark Arrestor Slipped							
9844	9844: Cap Very Badly Rusted, Hole in Cap Lid, Pipe Clamp Broken							
9845	9845: Spark Arrestor Slipped, Cap Rusty							
9846	9846: Pipe Badly Rusted, Pipe Seam Separating							
9847	9847: Cap Rusty, Pipe Separating							
9849	9849: Cap Tilted, Flashing Small Cracks, Spark Arrestor Rusted							
9851	9851: Cap Rusted, Pipe Dented, Spark Arrestor Rusted							
9852	9852: Illegal Modification, Spark Arrestor not to code, Parts Rusting							

Unit (9752-9919)	Chimney Sweeps report (June 2023)	Whole	Cap	Cap 2	Middle	Middle 2	Base	Other
9853	9853: Cap Badly Rusting, Flashing Cracked, Pipe Rusted							
9854	9854: Cap Rusty, Chimney Dirty, Spark Arrestor Damaged							
9855	9855: Flashing Poor, Cap Very Rusty							
9856	9856: Pipe Dented, Cap Rusty, Flashing Cracked							
9857	9857: Cap Rusty, Flashing Poor, Pipe Separated							
9858	9858: Clearance to Roof Issue, Cap Rusted							
9859	9859: Flashing Damaged, Cap Rusty, Pipe Rusted Badly							
9861	9861: Cap Rusty, Spark Arrestor Slipped							

Unit (9752-9919)	Chimney Sweeps report (June 2023)	Whole	Cap	Cap 2	Middle	Middle 2	Base	Other
9863	9863: Spark Arrestor Fully Slipped, Cap Rusty							
9865	9865: Spark Arrestor Slipped, Cap Very Rusty, Flashing Cracked							
9866	9866: Clearance to Roof Issue, Cap Rusty							
9867	9867: Cap Rusty, Clearance Issue, Spark Arrestor Damaged							
9868	9868: Cap Rusty, Spark Arrestor Damaged, Flashing Poor							
9869	9869: Cap Very Rusty, Spark Arrestor Damaged, Flashing Cracked							
9870	9870: Cap Rusty, Pipe Rusty							
9871	9871: Flashing Cracked, Cap Rusty							

Unit (9752-9919)	Chimney Sweeps report (June 2023)	Whole	Cap	Cap 2	Middle	Middle 2	Base	Other
9872	9872: Pipe Very Badly Rusting, Spark Arrestor Damaged, Cap Rusty, Flashing Poor							
9873	9873: Cap Rusty, Spark Arrestor Slipped, Flashing Poor							
9874	9874: Illegal Modification Made, Spark Arrestor not to Code, Clearance Issue, System Rusty							
9875	9875: Spark Arrestor Slipped, Clearance Issue, Cap Rusty							
9876	9876: Spark Arrestor Damaged, Cap Rusty, Flashing Crack							
9877	9877: Spark Arrestor Slipped, Pipe Separating, Cap Rusty							
9878	9878: Cap Rusty, Spark Arrestor Rusty							
9879	9879: Pipe Bracket Broke, Spark Arrestor Slight Slip							

Unit (9752-9919)	Chimney Sweeps report (June 2023)	Whole	Cap	Cap 2	Middle	Middle 2	Base	Other
9880	9880: Spark Arrestor Slipped, Flashing Cracked, Cap Rusty							
9881	9881: Cap Badly Rusting, Flashing Cracks							
9882	9882: Minor Rusting in Cap							
9883	9883: Clearance Issue, Cap Rusted							
9884	9884: Clearance Issue, Flashing Cracked, Cap Dented							
9885	9885: Cap Badly Rusted							
9886	9886: Clearance Issue, Spark Arrestor Rusting							
9887	9887: Cap Tilted, Cap Rusty, Flashing Cracked							

Unit (9752-9919)	Chimney Sweeps report (June 2023)	Whole	Cap	Cap 2	Middle	Middle 2	Base	Other
9891	9891: Clearance Issue, Chimney Dirty, Minor Rust on Cap							
9893	9893: Cap Rusty, Spark Arrestor Damaged							
9895	9895: Unknown Modification Made, Cap Rusting							
9903	9903: Spark Arrestor Damaged, Cap Rusty, Clearance Issue							
9905	9905: Spark Arrestor Damaged, Cap Rusty							
9907	9907: Cap Rusty, Pipe Separating							
9909	9909: Cap Rusty, Spark Arrestor Bent							
9911	9911: Spark Arrestor Slid, Cap Rusty, Clearance Issue							

Unit (9752-9919)	Chimney Sweeps report (June 2023)	Whole	Cap	Cap 2	Middle	Middle 2	Base	Other
9913	9913: Cap Rusty, Spark Arrestor Rusty, Flashing Cracked							
9915	9915: Spark Arrestor Bent, Flashing Cracked							
9917	9917: Spark Arrestor Slipped, Chimney Dirty							