

12/24/2013 PM Outside temp 57					
TIME	Room Temp	Cmbstr Therm	Thermostat	Flu Temp	Comments
6:30	57	80	High	380	New wood Live oak all <16%. Old wood was a tan oak mix 16-26%
7:30	65	75	Btwn High & Medium	300	
8:00	65.5	60	as above	280	Regardless of good wood, turning thermostat down even a little causes cat to drift into inactive and flue temp to drift below best operation into creosote zone
8:30	64	50	as above	200	ARRRRGH