





Notes: Front of house



Notes: Side of house and chase



Notes: Crack and buckle



Notes: Crack in joint



Notes: Remove old calk and remortar (pitch out)



Notes: Front flue





Notes: Center flue



Notes: Abandoned flue (towards back yard)



Label No rain guard on multi flue animal guard



Label Clean-out door (rust showing)



Label Abandoned flue entrance point



Label Eroded joints in firebox

Label

Label

Label

Label